DICKSON SL4/SK4

Temperature Chart Recorders

These units are self-contained temperature recorders. The SK4 & SL4 recorders are portable, easy-to-use and provide a permanent record of temperatures. These recorders have an ON/OFF switch, locking door and built-in slot for an optional tie-down cable and lock.

The SK4 was designed for use in applications where recording long term temperature trends is most important. The SL4 was built to give you the best of both worlds: a permanent record of long term temperature recording combined with an easy-to-read, digital display.



Specifications:

Measurement Ranges: -20 to +120°F, 0 to +100°F, +45 to +90°F, - 30 to +50°C

Ambient Operating Temperature: -22 to +122°F (-30 to +50°C); 0-95% RH (non-condensing)

Pen Accuracy: ±2% full scale SL4 Display Accuracy: ±3.6°F (±2°C)

Temperature Sensor: Precise spiral-wound bi-metallic strip transducer Power Supply: One "AA" alkaline battery, up to 3 years average life

Chart Movement: Battery operated

Average Response Time: 11 minutes to move 63% of full scale

Recording Times: 24 hour or 7 day

Chart Size: 4" DIA

Calibration: User: none; Factory: zero (no display calibration)

Display Type: LCD Resolution: 0.1°F (0.1°C) Mounting: Desk or wall mount

Enclosure: Black ABS

Dimensions: 7.0" x 5.5" x 2.5" (175mm x 137mm x 70mm)

Weight: 1 lb., 1 oz (482 g)

Approvals: CE

Includes: One "AA" alkaline battery, pen, one box of 60 charts, instruction manual and 1 pt. NIST Traceable Certificate of Calibration

DICKSON

DICKSON SL4/SK4

Ordering Information

Ordering Information

Temperature Range	Recording Time	SL4 \$229	SK4 \$199	Chart No. \$18/pkg.
-20 to +120°F	24 hour	SL4120F24	SK4120F24	
-20 to +120°F	7 day	SL4120F7	SK4120F7	C017
0 to +100°F	7 day	SL4100F7	SK4100F7	C012
+45 to +90°F	7 day	SL490F7		C070
-30 to +50°C	7 day	SL4350C7	SK44350C7	

Accessories

Accessones		
Description	Order No.	Price
Carrying Case	A708	
Tie-Down Cable		\$ 39
Pens (6 red)	A833	\$ 15
	P222	\$ 30
NIST Traceable Calibration 3-pt.*	N300	\$149
A2LA Accredited Calibration 3-pt.*	N400	
Two Year Extended Warranty		\$ 259
***	E200	\$ 99

^{*}Must be requested when ordering, add one week to delivery time.



www.dicksonweb.com

930 S. Westwood Ave., Addison, IL 60101-4917 • Toll Free Phone: 800.323.2448 • Toll Free Fax: 800.676.0498

All prices and specifications are subject to change

Made in U.S.A.

SL4/SK4 spec sheet rev. 01/02

Unpacking

container and contact Retain the original shipping report any damage to the carrier. obvious damage. Immediately the shipping carton for any signs of Carefully inspect the recorder and

> following items: Your recorder is shipped with the

- 2. One Point NIST Traceable 1. One box of charts Certification of Calibration
- One Operation Manual One "AA" alkaline battery

Statement of Accuracy

of the recorder an accuracy of ±2% full scale range temperature sensor for the pen has has an accuracy of ±2°F (±1°C). The temperature sensor for the display temperature sensing systems. The your recorder have independent the digital display and the pen on If you have purchased Model SL4,

Because of this independence it is

should be made at the average recording. See p.3 for instructions temperature that you will be match the display. The adjustment recommend adjusting the pen to pen. For greater accuracy we the display and the reading of the difference between the reading of SL4 to have up to a +5°F (+3°C) possible for a properly calibrated

Installation

a vibration-free surface. For best performance and longevity, the recorder is vertical and level on placed almost anywhere. Be sure Your portable recorder can be

corrosive fumes. Do not exceed environment—free from dust and temperature and humidity location should be in a clean specifications.

Specifications

Temperature Sensor:

bi-metallic strip transducer Precise, spiral-wound,

Pen Accuracy:

±2% full scale

Display Accuracy:

(SL4 only) ±2°F (±1°C)

Recording Time:

Average Response Time: 24-hour or 7-day

11 minutes to move 63% of full scale

Chart Size:

4" diameter

Ambient Operating Range: -22 to +122°F, -30 to +50°C

0 to 95% RH (non-condensing)

Power Supply:

One "AA" alkaline battery

Dimensions: 7" x 5.5" x 2.5" (175mm x 135mm x 70mm)

Chart Movement: Battery operated Weight: 1 lb., 1 oz. (482g)


Battery Life: One full year


Display sensor: ThermistorDisplay accuracy: ±2°F (±1°C)

N

ŭ,

Instrument Anatomy





Calibration/Pen Adjust

Your recorder was carefully tested and calibrated to factory specifications before being shipped. However, if your recorder indicates an obviously incorrect temperature, you may wish to readjust it by following these steps:

 Allow the temperature of the recorder to stabilize—usually about 15 minutes, or longer, depending on ambient temperature.

Turn the pen adjust screw (Fig. 1) with a small screwdriver until the tip of the pen is directly over the correct temperature mark on the chart.
 Your chart recorder is now accurately set.

Should recalibration become necessary, contact the seller for a Return Authorization Number and further instructions on returning the unit.

Operation and Maintenance

Recording Times Self-contained temperature recorders are available in 7-day or 24-hour configuration.

Chart installation If necessary, refer to section on "Paper Chart Installation".

Locking Door To open the door, simply press down the push button to release the latch. To permanently lock the door, remove the button and store it elsewhere. To remove it, grasp with thumb and forefinger and pull it up; it has a snug fit to prevent if from falling out.

Recording Place your Temperature Recorder where you want to record the temperature. Remove pen cap from pen tip. Activate On/Off switch.

Optional Tie-Down Cable At the bottom rear of the case you will see holes on either side of the case; these form the channel for the tie-down cable accessory. If you have purchased the cable, simply pinch the loop on one end of the cable to give it clearance into the channel, then thread it through the other end. Now you are able to lock or bolt down the unit.

Power Source Battery drives are designed to run approximately one year between battery changes. Replace with "AA" size alkaline battery.

Note: Replace pen cap when recorder is not in use.

٠

ěR.

Paper Chart Installation

- Open door of recorder case by pressing the push button release (located on top of case) to release lock.
- Remove the recorded chart if present.

7 days, depending on your recorder) simply repeat steps 1-5, replacing the

used chart with a new one.

5. Turn unit ON. (if it was turned off)

the correct time (and day for 7-day units) relative to the time index clip

At the end of one cycle (24 hours or

- Place a new chart on the chart hub—being certain that the edge of the chart slides under the chart guide clips located at the outside of the chart.
- 4. Set time by inserting a coin into the chart hub and turning clockwise to

Pen Installation

- Carefully lift the pen arm
- While holding the pen arm, use your thumb and forefinger to grasp the pen cartridge by the finger grips near the tip of the pen.
- Gently slide pen cartridge straight off pen arm.
- With the pen tip facing the chart, thread a new pen cartridge onto the pen arm. Slide the pen cartridge back until you feel the notch in the pen arm seat securely around the plastic cartridge of the pen tip.

- 5. Lower the pen on the chart
- If the pen arm is bent in the process, carefully bend the arm back so the pen contacts the paper
- Remove the pen cap and store on the pen cap holder on the unit.

Replacement Parts

The dataplate located on back of the recorder will give the proper chart number for your model. Your recorder is designed to use only factory supplied circular charts—the use of any

other brand invalidates the guaranteed accuracy of the instrument. Replacement pens can be economically reordered in six-pack quantities.

Condition

Charts (Box of 60 charts)

Quantity

1

Š	Incide to credit # D	
8	0	į
õ	0	1
es	Q	-
	a	·
	2	
	ē	
	9	
	5	
	6	
	76	
	0	
	is to that # printed on the center of the cha	
	5	
	===	
	printed on the center of the chart) Call	
	6	
	ots	
	me	
	Se	
	3	
	e fc	
	7.76	
	970	
	t) Call Customer Service for reorder or selection.	
	S JC	
	Sec.	
	Q	
	ب	

Replacement Pen Pack	6 red	P777
Alkaline "AA" Battery	Also a service amount as army marries in the	Ì
Tie-Down Cable		1711
Carrying Case	The state of the s	
NIST Traceable Certificate 1 point	3 100 100 100 100 100 100 100 100 100 10	
NIST Traceable Certificate, 3-point	The second secon	
ULTIMA :	TANK TANK THE TANK TH	NAS

Note: Before returning recorder for recalibration, please call Dickson Customer Service for "Return Authorization Number."

Problem	
Darri rate temperature races as si	Solution
maccurate temperature range or time period	Charts are not interchangeable Check temperature range & recording time
	instrument may need new clock or may be in need or calibration
Instrument is not running	Check On/Off switch
	Check proper battery installation Check motor: may be faulty return to factor.
Erratic movement of pen & reading	Place recorder on a level vertical surface that is vibration free
rei trace is to line of absent	Sand tip of pen or moisten or replace Deflect pen arm with thumb and forefinger until point just contacts the paper. Remove black pen cap
Chart speed is incorrect or chart is binding	Sand chart clips or pen lifting bar may be interfering with chart or faulty chart drive—Return to factory for repair (see Factory Service & Returns in manual for repair)
Out of Calibration or Questionable accuracy	Harsh environments or stressful conditions or time may cause the recorder to loose calibration and service or re-calibration may be needed.
Lost push outton latch	Door may be opened by inserting small screwdriver into push button opening Reorder replacement push button
Ospiay not iit on SL4	Battery is loose or dead Make sure battery is pressed tightly into the display
Display flashes or shows incorrect characters	Battery is weak and needs to be replaced

Factory Service and Returns

We recommend that damaged instruments be returned to our factory for complete repair. Before returning any instrument or package, please call for a "Return Authorization Number" (RA#).

When calling, please have the following information available

- out-of-warranty units.
- Serial number of unit.
- Model number of unit
- . The problem you're experiencing with unit

The Dickson Warranty

The Dickson Company warrants the TempTrace family of recorders will be free from defects in material and workmanship or accidental damage for a period of twelve months after delivery. In the event of a claim under this warranty, the product or part must be returned to the factory for repair or replacement (shipping prepaid) with a Return Authorization Number (See "Factory Service & Returns information above). It will be repaired or replaced at Dickson's option without charge.

The foregoing warranty and remedy are exclusive and in lieu of all other warranties either expressed or implied.

The Dickson Company shall not be liable for consequential or incidental damages resulting from failure or malfunction of its products. Products not manufactured by The Dickson Company are excluded from warranty.

Dickson manufactures a complete line of temperature, humidity, air quality & pressure instruments. Send or call for a free catalog of Dickson products.

Toll Free 1-800-323-2448



930 South Westwood Avenue * Addison, IL 60101 Telephone 630-543-3747* Fax 630-543-0498

MAN 12 Revised 12/96

•